



Motorcycle Manufacturer	P.G.O
Model	STAR 50 cc and STAR 2 50 cc
Issue	3/98 – rev. 00

Recommended position	Behind the front shield.
Power supply	Connect the positive supply wire of the alarm system to the RED/WHITE wire and the negative supply wire to the BLACK wire of the ignition lock.
Engine immobilisation (1)	Follow diagram A. Connect to the BROWN/BLACK wire that comes out of the ignition lock.
Ignition controlled positive supply	Connect to the ORANGE wire of the ignition lock.
Turn indicators	Connect to the PINK and BROWN wires of the front turn indicators.